

Title: Supplier Process Management Plan	Author: Byron Murray	Date: 5/29/2013
NEON Doc. #: NEON DOC 001158		Revision: A

## **Supplier Process Management Plan**

PREPARED BY (Name )	ORGANIZATION	DATE
Byron Murray	SYS	5/29/2013

APPROVALS (Name)	ORGANIZATION	APPROVAL DATE
Javier Marti	CCB Chair	6/12/2013
Krista Laursen	CCB Chair	6/11/2013
Laura Newton	CCB DIR SE	6/11/2013
Mike Stewart	CCB SE	6/12/2013

RELEASED BY (Name)	ORGANIZATION	RELEASE DATE
Stephen Craft	CCB Admin	6/12/2013

See Configuration Management System for approval history.

©2013 NEON Inc. All rights reserved.

The National Ecological Observatory Network is a project solely funded by the National Science Foundation and managed under cooperative agreement by NEON, Inc. Any opinions, findings, and conclusions or recommendations expressed in this material are those of the author(s) and do not necessarily reflect the views of the National Science Foundation.



Title: Supplier Process Management Plan	Author: Byron Murray	Date: 5/29/2013
NEON Doc. #: NEON.DOC.001158		Revision: A

# **Change Record**

<b>REVISION</b>	DATE	ECO#	DESCRIPTION OF CHANGE
Α	6/12/2013	ECO-01114	Initial Release



# **Supplier Process Management Plan**

NEON Form: NEON.DOC.001158

Supplier :		Facility/Location :		
NEON Quality :	Date :	Supplier's Quality Manager :		Rev Date :

Manufact	turing Process Matrix		Date:	Cuppiner 3 waanty manager .			ince Date .	
Step	turing Process Matrix Process	Mfg. Equipment, Fixture, Tools	Consumables	Feature Creation Controls	Verification/Validation Methods	Reference Specification and Supplier Document	Out-of-control reaction	
-								
-								
					+			
					+			
					+			
			+		+			
					1			

-				
-				
L				
-				
<u> </u>				
<b>-</b>				
-				
-				
-				
-				
-				



## **Supplier Process Management Plan**

NEON Form: NEON.DOC.001158

Supplier :			Facility/Location :	
NEON O liter .		D-4-	Compliants Constitut Management	Davi Data :
NEON Quality :		Date :	Supplier's Quality Manager :	Rev Date :

	Ifacturing Process Matrix	Mia Carrinmort	Canaumahlas	Footure Creatic:	Verification Melidetics	Deference	Out of control
Step	Process	Mfg. Equipment, Fixture, Tools	Consumables	Feature Creation Controls	Verification/Validation Methods	Reference Specification and Supplier Document	Out-of-control reaction
00	Material Ordering	NEON AVL	N/A	JDE system	N/A	NEON AVL	Contact supplier
10	Material Receipt	Labels Printer	Labels	Invoice	Check part number against AVL.	AVL	Quarantine part and inform Product Engineer/Supervisor.
				Packing List			
				JDE system			
20	IQA	Caliper	3M Transparent Tape 600	IPC-A-600	Checklist	IPC-A-600	Quarantine part and inform
		Pin Gauge		Part Receiving Checklist		AVL	Product SQE and IQA Enginner/Supervisor.
		Microscope (Olympus)		(682F230)		NEON Drawings	Non Conforming Material
		Mitutoyo Microscope		Part Inspection Instruction (682F244)			
		Profile Projector (PJ3000)					
		Height gauge					
		Granite block					
30	Material Release	N/A	N/A	JDE system	N/A	Pick List	Quarantine part and issue new part.
				Production Order Pick List			new part.
40	Material Staging	N/A	N/A	SFDM	Pick List Verification	Pick List	Quarantine part and issue
40	Material Staging	IN/A	IN/A	Production Order Pick List	PICK LIST VEHICATION	PICK LIST	new part or call Production Engineer.
50	Pre-Depanalization	Slice Cutter	N/A	"Depanelization" in On-Line Documentation.	N/A	On-Line Documentation	Stop the process and inform Production
				Documentation.		NEON Drawings	Supervisor/Technician.
51	Cut Trace	Exactor Knife	Epoxy EP-01	"Cut Trace" in On-Line	LCR Meter Verification	On-Line Documentation	Stop the process and inform Production
		Microscope Micro Drill	MSDS 680	Documentation. 692T007		NEON Drawings	Supervisor/Technician.
				0921007			
60	Screen Printing	MPM Screen Printer (UP	Solder Paste (Kester 562)	"First Assembly or Second	SPC control on solder paste	PCBA Gerber File	Stop the process and inform
		2000/AP-21/AP-HIE) LSM	Clean agent (SWAX and	Assembly" in On-Line Documentation.	height inspect and measure.	On-Line Documentation.	Production Supervisor/Technician.
		Stencil	440R)	Procedure 621T027	Solder Paste Height Records		(system automatically notifies technician)
		Alex Ultrasonic	Wiper paper (C-100)	WI-192			
		Batch cleaning	SOP 79	MPM software			
		Smartsonic 5000		INI INI SOILWAIG			

70	Chip Placement	Fuji CP-642, CP-65, CP-643, Mydata MY19E or Genesis C30	N/A	"First Assembly or Second Assembly" in On-Line Documentation.	SMT Conversion Checklist.  Component Change Log	On-Line Documentation.	Stop the process and inform Supervisor/Technician
				Fuji software			
				Maintenance records			
				WI-265			
80	IC Placement	Fuji IP-3, GSM or Mydata MY	N/A	"First Assembly or Second	SMT Conversion Checklist	On-Line Documentation.	Stop the process and inform
		19E		Assembly" in On-Line Documentation.			Supervisor/Technician.
				Fuji software	Component Change Log		
				Maintenance records			
				WI-265			
81	Manual Placement	ESD Plastic Twizzle	N/A	"First Assembly or Second	SFDM	On-Line Documentation.	Stop the process and inform
	Manual Flacement	LOD Flastic TWIZZIE	IVA	Assembly" in On-Line Documentation.	SI DIW	On-Line Documentation.	Supervisor/Technician.
90	Reflow	HVN-102 Conceptronic Oven, Heller	N/A	"First Assembly or Second Assembly" in On-Line	N/A	On-Line Documentation.	Stop the process and inform Process Engineer.
		9200 or Omniflex		Documentation.			Trocco Engineer.
		Datapaq Profiler		Profileer software			
				Maintenance records			
				WI-265			
100	Post Reflow Inspection	Microscope	N/A	"First Assembly or Second Assembly" in On-Line Documentation.	SFDM	IPC-A-610	Inform production supervisor.
		Visual Template				0.11. 5	
				WI-265		On-Line Documentation.	
110	Auto Inspection	MVP Ultra III	N/A	AOI in Online Document	SFDM	Machine program	Stop the process and inform
					Storm	IPC-A-610 Class II	Production Supervisor/Technician.
120	Auto Insertion	Universal 6241B or Radial 8 2.5/5	N/A	"Al" in On Line Documentation.	Al Conversion Checklist	On-Line Documentation IPC-A-610	Stop the process and inform Production Supervisor.
				Component Station List			
				Maintenance records			
				WI-265			
130	Depanalization	Router Machine - ATI 101 CM	Router Milling Bit	"Depanelization" in On-Line	N/A	On-Line Documentation	Stop the process and inform
		or GETech ESR-1000		Documentation.		NEON Drawings	Production Supervisor/Technician.
140	Manual Insert	MI station	N/A	"Manual Assembly" in On-	Wave Solder Checklist	IPC-A-610	Stop the process and inform
		Wave Pallet		Line Documentation.			Production Supervisor/Technician.
				WI-265			

150	Wave Soldering	Electrovert Ultrapack 600C	Solder (Sn63Pb37)	"Wave Solder" in On-Line Documentation.	N/A	On-Line Documentation.	Stop the process and inform Production
		Vitronics Soltec	Flux (Kester 2331ZX)			NEON Drawings	Supervisor/Technician.
		Wave Pallet		Maintenance records			
		Datapaq Profiler		Profile software			
				WI-265			
160	Wash	Electrovert H-500 SMT	DI water	Shiftly monitoring on cleaning efficiency.	lonograph 500 M	IPC-A-610	Stop the process and inform Production
		Triton IV MII SMT					Supervisor/Technician.
				Maintenance records			
				WI-265			
170	Wave Visual Inspection	Microscope	Cleaning agent – Vericlean	"Inspection" in On-Line Documentation.	SFDM	IPC-A-610	Inform production supervisor
		Visual Template					
				WI-265			
						On-Line Documentation	
180	5DX (side1 & side 2)	Agilent	Carrier	"5DX" in On-Line Documentation.	SFDM Storm	Machine program, IPC-A- 610 Class II, SMT Solder	Stop the process and inform Production
					Papeless Repair Station	Joints, Plated Through-Hole	Supervisor/Technician.
				WI-265	"PLR"	Components, Missing Component and Pcap	
						Orientation.	
190	Manual Soldering and Assembly	Metcal Soldering Iron	Cleaning agent – Vericlean	"Manual Soldering & Assembly" in On-Line	SFDM	IPC-A-610	Stop the process and inform Production
	Assembly	Hand Soldering Tools		Documentation.			Supervisor/Technician.
		Ionizer (Desco)	Flux (952-D6)	WI-265			
		Hand Soldering Jig	Solder Wire (No clean, Flux- 245)			On-Line Documentation	
		Torque Driver	-,				
200	F: 116: 11 c		121/0	"NA 10 11 : 0	SFDM	IPC-A-610	
200	Final Viaual Inspection	Microscope	N/A	"Manual Soldering & Assembly" in On-Line	SFDM	IPC-A-610	Stop the process and inform Production
				Documentation.			Supervisor/Technician.
				WI-265		On-Line Documentation	
040	0.4.00	l de	121/0	#0.4.00": O 1:	OFDIA		
210	QA02	Microscope	N/A	"QA02" in On-Line Documentation.	SFDM	IPC-A-610	Inform QA Supervisor
				WI-265			
						On-Line Documentation.	

220	ICT Test	HP3065, HP3070, Takaya or Test Fixture	N/A	"HP3065, HP3070, Takaya or Test Fixture" in On-Line Documentation	SFDM	Customer specification	Inform technician if three consecutive failure
				Maintenance records WI-265			
230	Conformal Coating	Besin	Alcohol	SOP 22	SFDM	IPC 610D	Inform Production Supervisor.
		Tank					
240	Hardware 1	Torque Driver  Metcal Soldering Iron	N/A Flux (952-D6)	"Hardware" in On-Line Documentation.	SFDM	IPC-A-610	Inform Production Supervisor.
		Hand Soldering Tools	Solder Wire (No clean, Flux- 245)	WI-265		On-Line Documentation.	
250	QA03	Microscope	N/A	"QA03" in On-Line Documentation.	SFDM	IPC-A-610	Inform QA Supervisor
				WI-265		On-Line Documentation.	
260	Hardware2	Torque Driver  Metcal Soldering Iron	N/A Flux (952-D6)	"Hardware" in On-Line Documentation.	SFDM	IPC-A-610	Inform Production Supervisor.
		Hand Soldering Tools	Solder Wire (No clean, Flux- 245)	WI-265		On-Line Documentation.	
270	Functional Test	NEON FT Fixture / Tester	Cleaning agent – Vericlean	"FT" in On-Line Documentation Maintenance records	SFDM	Customer specification	Inform technician if three consecutive failure
				WI-265			
280	Hi-POT	Extach 7140 AC/DC	N/A	"Hi-POT" in On-line	SFDM	Customer specification	Debugged by Technician
		Withstand Voltage Tester		Documentation  Maintenance records	Pass/Fail criteria		
				WI-265			
290	SI/QA04/CQA	Microscope	N/A	"SI/QA04/CQA" in On-Line Documentation.	SFDM	IPC-A-610	Inform QA Supervisor
				WI-265		On-Line Documentation.	
300	Packaging	Label Printer	Nesting, Carton box, Packing Material, Labels.	Documentation.	SFDM	RM0002 standards	Inform Production Supervisor.
				WI-265			
310	Shipping	Label Printer	Shipping Label	Customer address and shipping Information.  JDE system	Invoice System verification of each individual board.	N/A	Inform Shipping Supervisor/Program Manager/QA Engineer.

#### Supplier Process Management Plan Reference Table

01	Burney	Model							
Step	Process	Part Number XXX	Part Number XXX	Part Number XXX					
00	Material Ordering	~	<b>~</b>	<b>~</b>					
10	Material Receipt	<b>✓</b>	~	~					
20	IQA	~	<b>~</b>	~					
30	Material Release	>	<b>~</b>	<b>~</b>					
40	Material Staging	<b>&gt;</b>	<b>~</b>	<b>~</b>					
50	Pre-Depanalization								
51	Cut Trace								
60	Screen Printing	>	<b>~</b>	<b>~</b>					
70	Chip Placement	<b>&gt;</b>	<b>~</b>	<b>~</b>					
80	IC Placement	~	<b>~</b>	~					
81	Manual Placement								
90	Reflow	~	<b>~</b>	~					
100	Post Reflow Inspection	~	<b>~</b>	~					
110	Auto Insertion								
120	Depanalization	~	<b>~</b>	~					
130	Manual Insert	~	<b>~</b>	~					
140	Wave Soldering	~	<b>~</b>	~					
150	Wash	~	<b>✓</b>						
160	Wave Visual Inspection	~	<b>✓</b>	~					
170	5DX (side1 & side 2)								
180	Manual Soldering and Assembly	~		~					
190	Final Visual Inspection	~		~					
200	QA02								
210	ICT Test	~	~	<b>~</b>					
220	Hardware/Hardware 1								
230	QA03								
240	Hardware2								
250	Functional Test								
260	Hi-POT								
270	SI/QA04/CQA	~	<b>✓</b>	<b>~</b>					
280	Packaging	<b>✓</b>	<b>✓</b>	<b>~</b>					
290	Shipping	<b>✓</b>	~	<b>~</b>					

1	1	1		1	1	
						_